Release Notes

CY3677 Evaluation Kit

Release Date: December 23, 2016

Thank you for your interest in the CY3677 Evaluation Kit. This document lists kit contents, installation requirements, kit documentation, limitations and known issues with the kit.

Kit Contents

The CY3677 Evaluation Kit includes the following:

- CY3677 Evaluation Board
- USB Standard-A to Mini-B cable
- Quick Start Guide

Software and Tools

The Example Projects included in the kit software require ClockWizard 2.1 or later. This is available with the kit installer or can be downloaded from the CY3677 Evaluation Kit webpage.

The Example Projects also requires the PSoC Programmer 3.25 or later. This is available with the kit installer or can be downloaded from the PSoC Programmer webpage.

Installation

Installation instructions are provided in the Kit Guide, available at www.cypress.com/CY3677

Example Projects and Kit Collateral

The CY3677 Evaluation Kit webpage includes the kit installation packages, DVD image (ISO), and setup files (EXE) to install the examples projects, documents, and hardware files of this kit. Refer the Kit Guide included in the kit installer, or the kit webpage for more details on the hardware and examples.

Kit Revision

This is Rev. *A version of the CY3677 Evaluation Kit. This release comes with ClockWizard 2.1 GUI application and Example Projects created using this software application.

Limitations and Known Issues

None

Documentation

The kit documents are located in the `Documentation` folder in the installation directory. The default location for the kit documents is:

<Install_Directory>\CY3677 Evaluation Kit\<version>\Documentation

Documents include:

- *CY3677_Kit_Guide.pdf*
- *CY3677_Quick_Start_Guide.pdf*
- *CY3677_Release_Notes.pdf*

Silicon Errata

The silicon does not have an errata. Refer to the CY29430 datasheet available at www.cypress.com/HPO

Technical Support

For assistance, go to www.cypress.com/support or contact our customer support at +1 (800) 541-4736 Ext. 2 (in the USA), or +1 (408) 943-2600 Ext. 2 (International).

Additional Information

For more information about ClockWizard 2.1 visit webpage

For more information about PSoC Programmer and supported hardware visit the PSoC Programmer webpage www.cypress.com/psocprogrammer

Cypress Semiconductor
198 Champion Court
San Jose, CA 95134-1709
Phone(USA): 800.858.1810
Phone (Intnl): +1.408.943.2600
www.cypress.com

Copyrights

Flash Code Protection

Cypress products meet the specifications contained in their particular Cypress PSoC Datasheets. Cypress believes that its family of PSoC products is one of the most secure families of its kind on the market today, regardless of how they are used. There may be methods, unknown to Cypress that can breach the code protection features. Any of these methods, to our knowledge, would be dishonest and possibly illegal. Neither Cypress nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Cypress is willing to work with the customer who is concerned about the integrity of their code. Code protection is constantly evolving. We at Cypress are committed to continuously improving the code protection features of our products.